
REVISIONS

CHECKED BY | LRM

SITE PLAN



ADA SPACES

TOTAL

BENCHMARK:

THE BENCHMARK USED FOR THIS SURVEY IS A STANDARD DISK SET INTO A DRILL HOLE INT HE TOP OF THE SOUTH ONE OF THREE CONCRETE FOUNDATIONS FOR THE LARGE SHELL SIGN, 94.5' EAST FROM THE EDGE OF OIL FOR DILLON DAM ROAD, 58.1' NORTH FROM THE NORTHWEST CORNER OF A BUILDING AT 1121 SUMMIT BOULEVARD, 10.5' NORTH FROM A WITNESS POST, 0.8' WEST FROM THE WESTERN CORNER OF THE IRON BASE OF THE SOUTHERN SIGN POST AND ABOUT 26.2' BELOW INTERSTATE 70. ELEV.=9058.09 (NAVD 88)

BASIS OF BEARING:

BEARINGS SHOWN HEREON ARE ASSUMED AND ARE BASED UPON THE NORTHWESTERLY LINE OF LOT 2A, RESUBDIVISION OF LOT 2, BLOCK A, DISCOVERY INTERCHANGE WEST WHICH BEARS N51°44'53"E BETWEEN THE MONUMENTS SHOWN HEREON.

LAND USE SUMMARY SNOW STORAGE **PAVEMENT** TOTAL LOT COVERED NON-COVERED CONDITION AREA (SF) AREA (SF) AREA (SF) AREA (SF) (SF) 62,037 85,460 44,711 130,171 19,200 (15%) **EXISTING** (48%) (66%)(34%) 45,579 60,561 84,592 130,171 19,276 (15%) **PROPOSED** (46%) (65%)(35%)

116

6

128

127

CALL 811 2 BUSINESS DAYS PRIOR TO DIGGING, GRADING OR EXCAVATING FOR MARKING OF UNDERGROUND MEMBER UTILITIES.

JFSA ASSUMES NO RESPONSIBILITY FOR UTILITY LOCATIONS. THE UTILITIES SHOWN ON THIS DRAWING HAVE BEEN PLOTTED FROM (PROVIDED) ASCE (38) UTILITY QUALITY LEVEL D (QLD) AVAILABLE INFORMATION. IT IS, HOWEVER, THE CONTRACTOR'S RESPONSIBILITY TO FIELD VERIFY THE SIZE, MATERIAL, HORIZONTAL AND VERTICAL LOCATION OF ALL UTILITIES (DEPICTED OR NOT DEPICTED) PRIOR TO THE COMMENCEMENT OF ANY CONSTRUCTION.